

FIG. 1





FIG. 2




FIG. 3**FIG. 4**

FIG. 5



5/20

FIG. 6




FIG. 7A






FIG. 7B




6/20

FIG. 8



7/20

FIG. 9



8/20

FIG. 10A





FIG. 10B



9/20

FIG. 11A





FIG. 11B



10/20

FIG. 12A

ELECTRODE POSITION: 30mm DOWNSTREAM





FIG. 12B



11/20

FIG. 13A




FIG. 13B




FIG. 14





FIG. 15

—◆— 10mm UPSTREAM
—■— 10mm DOWNSTREAM

FIG. 16A




FIG. 16B




FIG. 16C




FIG. 16D




FIG. 16E





FIG. 16F








FIG. 18

FIG. 19






FIG. 20

FIG. 21A

$\begin{cases} m=4 \\ n=5 \end{cases}$




FIG. 21B

$\begin{cases} m=3 \\ n=5 \end{cases}$




FIG. 21C

$\begin{cases} m=3 \\ n=5 \end{cases}$




FIG. 21D

$\begin{cases} m=3 \\ n=6 \end{cases}$




FIG. 21E

$\begin{cases} m=1 \\ n=2 \end{cases}$




FIG. 22A

METAL ROLLER




FIG. 22B

METAL BRUSH




FIG. 22C

METAL SHEET




FIG. 22D

METAL SHAFT




FIG. 22E

METAL BLOCK



FIG. 22F

METAL PLATE




FIG. 22G

METAL BLADE

